

# AUSTIN-HEALEY

## TRAFFICATOR (CONTROL HEAD) REBUILDING SERVICE



I have been rebuilding Austin Healey Trafficators for over 20 years and have restored dozens of units over this time for friends, club members and several Austin Healey restoration shops. I have recently expanded my services since the former provider of this service, Vic Wright of Portland Oregon, is no longer accepting new business.

All units received are inspected, dismantled and a price is quoted. Provided the Bakelite pieces are not chipped or broken, they are restored to bring back their original luster and beauty. Internal parts are cleaned inspected for wear, replaced if missing, repaired if necessary, and lubricated before reassembly. Chrome parts are plated as required for an additional charge.

For adjustable steering column units I advise that you send everything (including just the upper sliding tube section) complete and attached to include the original wiring harness. I will inspect the adjustable stator tube head and then clean and lubricate it. If a new or reusable original wiring harness is provided I will wire the unit and reattach the short stator tube prior to returning. Please do not attempt to send me the long non adjustable stator tube. It is important that you FIRST call me before removing any parts from your car. I will provide you detailed instructions, including how to pack for mailing.

Basic labor charge for rebuilding a complete unit is \$150.00, providing extensive repairs to the Bakelite pieces are not required. The hourly labor rate is \$25.00 for additional repairs as required. Any replacements for missing or damaged parts are extra, and while some new parts are being produced and can be procured (items such as horn buttons and horn springs,) I also have certain used spares plus, NOS (new old stock) parts. The availability of broken or missing parts can be very limited at times, and is not guaranteed.

I also have a limited number of rebuilt units available for sale from time to time. Call or e-mail me for details.

Contact: **Curt Arndt**  
**3215 Via Cajita**  
**Carlsbad, CA 92010-1394**  
**(760) 458-1926 cell**  
[cnaarndt@gmail.com](mailto:cnaarndt@gmail.com)

This document was created with Win2PDF available at <http://www.win2pdf.com>.  
The unregistered version of Win2PDF is for evaluation or non-commercial use only.  
This page will not be added after purchasing Win2PDF.